

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue Seattle, Washington 98101

August 9, 1995

Facility file 4(a)

MEMORANDUM

To:

Facility Files

From: Kevin Schanilec, CERCLA Off-site Coordinator

Subj: Non-Financial Record Reviews for Off-site Facilities

This memorandum documents the periodic evaluation of the facilities listed below regarding their Off-site acceptability.

1. Burlington - Pier 91 (WAD 00081 2917)

This facility was last inspected 4/13/95 by the Washington State
Department of Ecology (Ecology). A written informal warning was issued
regarding a minor compliance issue involving labelling of a container, which
was corrected. Based on the above, it is determined that these violations are
not relevant violations that would impact the facility's Off-site status, and
that this facility remains acceptable for CERCLA Off-site waste.

2. Burlington - Lucille (WAD 00081 2909)

This facility was last inspected 5/31/95 by the Washington State Department of Ecology (Ecology). A written informal warning was issued regarding the implementation of their contingency plan. This issue has been properly addressed. Based on the above, it is determined that these violations are not relevant violations that would impact the facility's Offsite status, and that this facility remains acceptable for CERCLA Off-site waste.

3. Burlington - Tacoma (WAD 02025 7945)

This facility was last inspected 5/2/95 by the Washington State Department of Ecology (Ecology). No violations were found during the inspection. Based on the above, it is determined that these violations are not relevant violations that would impact the facility's Off-site status, and that this facility remains acceptable for CERCLA Off-site waste.

4. Burlington - Washougal (WAD 09230 0250)

This facility was last inspected 5/3/95 by the Washington State Department of Ecology (Ecology). No violations were found during the inspection. Based on the above, it is determined that these violations are not relevant violations that would impact the facility's Off-site status, and that this facility remains acceptable for CERCLA Off-site waste.

5. Chemical Waste Management (ORD 08945 2353)

This facility was last inspected 1/23/95 by the Oregon State Department of Environmental Quality. No violations were found during the inspection. Additionally, this facility is currently under the Environmental Leadership Project, which will monitor compliance at the facility. Based on the above, it is determined that these violations are not relevant violations that would impact the facility's Off-site status, and that this facility remains acceptable for CERCLA Off-site waste.

6. ESII Site B (IDD 07311 4654)

This facility was last inspected 3/29/95 for TSD areas and 7/7/95 for groundwater issues by the Idaho Division of Environmental Quality. No violations were found during the inspections. Based on the above, it is determined that these violations are not relevant violations that would impact the facility's Off-site status, and that this facility remains acceptable for CERCLA Off-site waste.

